

Abstract to the lecture course "Engineering Graphics"
The section "Drawings"

In general lectures dealt separable and permanent connection. What unites these themes and the difference between them. Wheel gear. Features design and calculation of parameters of gear wheels. General requirements for registration of course work. General requirements for the explanatory note of course work and completion of major sections. Particulars of the details of threaded parts. Designation mark or image in the drawing. Making drawings of details of the "shaft". General requirements for the application size. layout drawing of cast parts such as "cover" and "Case". Selecting the main difference is the type kind of details. Features of the application size and roughness of casting parts. General requirements for registration of assembly drawings and specifications.